



---

# Smoke and Dye Testing Summary

---

## High Level Sewershed

### Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-129	Smoke	10/21/2008	ADS/TM	S09MM_008MH	Dry	Yes	711.09

### Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S09MM_008G1	S09MM_008MH	S09MM_002MH	248.4782	8
S09MM_002G1	S09MM_002MH	S09MM_015MH	200.2533	10
S11MM_027G1	S11MM_027MH	S11MM_041MH	79.42284	8
S09MM_015G1	S09MM_015MH	S11MM_041MH	182.9381	10

### Observations & Photos

**Obs\_ID** S1028-129-OB01

**Address** 3309 Gwynns Falls Pkwy


**Status** Private

**Source** Cleanout

**Location** Yard - front

**Nearest MH** S09MM\_008MH

**Comments** Smoke from cleanout in front yard. 3309 Gwynns Falls Pkwy.



**Picture** \S1028-129-OB01-P01.jpg

**Comments** Front of house, 3309 Gwynns Falls Pkwy.

**Obs\_ID** S1028-129-OB02

**Address** 3305 Gwynns Falls Pkwy


**Status** Private

**Source** Cleanout

**Location** Yard - front

**Nearest MH** S09MM\_002MH

**Comments** Smoke from cleanout in front yard. 3305 Gwynns Falls Pkwy.



**Picture** \S1028-129-OB02-P01.jpg

**Comments** Front of house, 3305 Gwynns Falls Pkwy.